


Slope Stabilization Strategy

Bank Stabilization And Creek Works Enlargement Plan






Vegetated Rock Revetment with Native Willow Stakes and Woody Debris



Boulder and Woody Debris Bed Feature for Fish Habitat

Rumble Pond Park South Trail






























Images Of Creek Stabilization and Restoration Work

1+2 Example Of Vegetated Rock Revetment

3 Fish Habitat Elements Boulder and Woody Debris Bed Feature

Section AA through Bank Stabilization and Boardwalk

New Boardwalk





Planning and Infrastructure Department Infrastructure Delivery Services Division





Fish Habitat Elements Boulder Weir Feature

